

Tech Report 5/23/25

Cruisers: RF Camber was inspected.

- The #14 was DQ for being $\frac{1}{2}$ inch over

6 Shooters: The RF and LF camber were inspected. All passed

Street Stocks: Roof height, quarter height, and nose height were inspected. All Passed